


B-COMM

Release Notes

Version 5.8.0



Overview

A new B-COMM version has been released. The new version 5.8.0 replaces the previous version 5.7.1.

News/Changes/Revisions

TANlock:

- TANlock devices with the following versions are supported:
 - **HW-Version 3.1.1**
 - **FW-Version 5.1.0**
- A new client type "TANlock Client" has been added for TANlock-based streams and devices.
- The following functions have been implemented in BCOMM GUI to support TANlock devices:
 - Stream /device configuration,
 - Device information, and
 - Device actions

GUI:

- **SpeedUp**
Improvements have been implemented to accelerate the loading and launching of the B-COMM GUI. (Speed Up) The loading speed has been increased by a factor of 5. The GUI loading process is now also visually indicated.
- **Install wizard**
Improvements have been made to the installation wizard for gateways with components.
- **Fixed bugs**
 - Some program numbers for newer devices were missing from the SHC export logic. This resulted in empty fields for the SSH key. This has been fixed.
 - An error occurred when using an SSH key that already existed in BCOMM/SSHKeys but was being used by someone outside of that folder. Now, we check not only the name of the key but also its content. If it is the same key, no error occurs, and the process continues.
 - Some subterminal program numbers were not being extracted correctly from the configuration file. This has been fixed.
 - Remove the hardcoded 55 attempts in Application.java and add calculations to determine the application interface reconnect time based on the configuration. This way, the response while loop will only stop after the shutdown process (connection not possible) is complete.
 - Terminal Basic Settings checks for the device type and initially uses the admin user if the device type is AC30.

PEC/AC:

- **GUI configurator**
 - Using terminals with a higher resolution than the laptop caused problems. The window now has scroll bars for navigation within the display.


- **Digital Wallet:**
 - Configuration support for Apple Wallet and Google Wallet for Controller 92xx-K7 AC30 has been added starting with firmware version 680-06-X-K00.

Helper:

- **TANlock Integration**
 - B-COMM Helper communication with TANlock devices via HTTP/TCP has been implemented, enabling the execution of requests via the Helper interface.

Security updates / Update libraries

- The LEGIC Connect API has been updated to the Trusted Service API V14.
- The external libraries used and integrated are subject to constant review. The list is constantly being revised and this list can be viewed for each version in the info tab "Third-party libraries/licenses...".



Known issues

- The wizard is currently still unavailable for the combination of CardLink components with MIFARE technology.
- Display errors occur when using all current OpenJDK LTS versions. Non-LTS versions or older LTS versions display the user interface as before. We are working hard on a solution.

Installation/Update

Distribution

- The new B-COMM version 5.8.0. is available for download on the dormakaba portal.

For further questions or information on these release notes, please contact the Business Services and Business Development departments.

dormakaba Deutschland GmbH

Albertstr. 3, 78056 Villingen-Schweningen, Deutschland

T: +49 (0) 7720 603-0

www.dormakaba.com

Contact

Business Services

awm.info.de@dormakaba.com

Heinz Hoffmann

Product Manager

heinz.hoffmann@dormakaba.com

+49 7720 603 227